
## B&W 801 Series 80

S/N 1251 & 1252 January 1980 → August 2018






## S/N 1251 & 1252

HF+LF XO board is marked 1283 & 1284

After soldered-in relay (s/n 901)

Before 1000uF protection cap (s/n 1587)

Before 801F fibre-crete head (s/n 4001)



LF enclosures "18 Jan 1980"

EQ board "tested 22 Jan 1980"

XO component date codes 7944, 8001, etc



LF & HF crossover board "issue 5"

MF crossover board "issue 3"

Very discolored around power resistors (esp on MF)

## Mods

- Disconnect the protection circuit and bypass the relay
- Bi-Amp: HF+MF on separate input from LF (including separate ground)
  - New binding posts underneath bass unit
- Replace most crossover components
  - Capacitors Solen PP everywhere, and Mundorf for HF input
  - Resistors Vishay-Mills MRA12 1% (non-inductive 10W)
  - Inductor Solen 2.3mH aircore for MF
- Misc/Cosmetic
  - Scrape & oil bass cabinet (condition was OK, minor dings)
  - Raam deadening mat in MF & LF enclosures
  - Sand & re-paint MF+HF head cabinet
  - New grill cloth from Huntley Audio on ebay
  - Foam OK; remove protection battery & add auralex foam in its place.

